



www.autodiagnos.com

VDO Autodiagnos Check

May 2019 - Software version 01.09

VDO are pleased to announce the release of the latest software for your VDO Autodiagnos Check service tool.

We're always making changes and improvements to make your tool better for you. For this release, we adapted our schedule and concentrated on solving a bug that caused the handset to reboot under certain conditions.

If you have not yet updated your tool from the December release, take a look at the latest functions, coverage and other benefits your Autodiagnos Check tool can now offer you on the following pages. We're sure you'll agree that it will be highly beneficial for your everyday workshop tasks.

For a full list of the supported makes and models, please click the application list available on www.autodiagnos.com.

Kind regards
Your VDO Team

* This basic product information provides general information about products which may not (yet) be included in the product portfolio but are basically available. Versions and functionalities can deviate from this general information. All rights for the patent, utility model or design registration are reserved.

VDO



Service can be this easy

Updates and changes

EPB Service Functions

- **Mazda** Models affected:

– Mazda 6	2015-2017	– Mazda CX-5	2015-2017
– Mazda 3	2016-2017	– Mazda CX-9	2017-...
- **Jaguar** Models affected:

– XF (X260)	2015-...	– XF (X250)	2008-2015
– XE	2015-...	– F-Pace (X761)	2016-...
- **Jeep** Models affected:

– Renegade	2014-...		
------------	----------	--	--
- **Fiat** Models affected:

– 500X	2015-...		
--------	----------	--	--

The Autodiagnos Check supports brake service functions for over 20 manufacturers and EPB is supported on all Jaguar and Land Rover models up to 2017.

Injector Configuration Service Functions

For the following models, injector programming service functions has been added or updated.

- **VAG** Models affected 2009-2017:
 - Diesel Engine 1.6 Liter TDI (TP2.0)
- **Audi**

– A1	– A3 Cabriolet
– A1 Sportback	– A3 Sportback
– A3	
- **Seat**

– Altea	– Ibiza IV ST
– Altea XL	– Leon
– Ibiza IV	– Toledo IV
– Ibiza IV Sportcoupe	
- **Skoda**

– Fabia II	– Roomster
– Fabia II Combi	– Roomster Praktik
– Octavia II	– Superb II
– Octavia II Combi	– Superb II Kombi
– Rapid	– Yeti
– Rapid Spaceback	
- **VW**

– Beetle	– Golf VI Cabriolet
– Beetle Cabriolet	– Golf VI Variant
– Caddy III Kasten	– Jetta III
– Caddy III Kombi	– Jetta IV
– Caddy IV Kasten	– Passat
– Caddy IV Kombi	– Passat Variant
– Golf Plus	– Polo
– Golf VI	– Touran
- **Ford** Models affected:

– C-Max II	2010-...	– Ranger	2011-...
– Fiesta VI	2008-...	– S-Max	2006-2014
– Focus II	2004-2013	– Transit	2006-...
– Focus III	2010-...	– Transit	2013-...
– Galaxy	2006-2015	– Connect	2013-...
– Kuga I	2008-...	– Mondeo IV	2007-2015
– Kuga II	2012-...	– Focus C-Max	2003-2007
- **Opel** Models affected:

* This basic product information provides general information about products which may not (yet) be included in the product portfolio but are basically available. Versions and functionalities can deviate from this general information. All rights for the patent, utility model or design registration are reserved.

VDO



Service can be this easy

- All variants of Movano B (X62)
- **Peugeot/Citroen (PSA) Models affected:**
 - Citroen Jumper III / Relay III 2006-...
 - Peugeot Boxer III (U9) 2006-...
 - Citroen Berlingo (B9) 2008-2018
- **Mercedes Models affected:**
 - B-Class (W246, W242) 2013-...
 - A-Class (W176) 2012-...
 - GLA-Class (X156) 2014-...
 - CLA Coupe (C117) 2013-...
 - CLA Shooting Brake (X117) 2015-...
 - Citan Kombi / Tourer (415) 2013-...
 - Citan Mixto (415) 2013-...
 - Citan Kasten (415) 2013-...

Mercedes

Service Reset functionality added

- Models affected:
 - S-Class (W222)
 - E-Class (W213)
 - Citan (W415)
 - Vito (W447)
 - Sprinter (W907)
 - X-Class (W470)
 - Smart Fortwo (453)
 - Smart Forfour (453)

Model year update upto 2018

- Supported functions:
 - Reads and deletes DTCs
 - Shows live data
- Models affected
 - Passenger cars:
 - A-Class(169, 176)
 - B-Class (245, 246)
 - C-Class (204, 205)
 - CLA-Class (117)
 - CLC-Class (203)
 - CL-Class (216)
 - CLS-Class (218, 219)
 - E-Class (211, 212, 213)
 - E-Class Coupe (207, 238)
 - S-Class (221, 222)
 - S-Class Coupe (217)
 - SL-Class (230, 231)
 - SLK-Class (171, 172)
 - SLS-Class (197)
 - R-Class (251)
 - SUVs:
 - G-Class (461, 463)
 - GLA-Class (156)
 - GLC-Class (253)
 - GLE-Class Coupe (292)
 - M-Class(164, 166)
 - Smart:
 - Smart Fortwo (451, 453)
 - Smart Forfour (453)
 - Vans:
 - Citan (415)

* This basic product information provides general information about products which may not (yet) be included in the product portfolio but are basically available. Versions and functionalities can deviate from this general information. All rights for the patent, utility model or design registration are reserved.

VDO



Service can be this easy

- Vito/V-Class (447)
- Sprinter II (906)
- X-Class (470)
- Vito/Viano/Valente (639)

Ford

Extended existing coverage for new models up to 2017:

- Supported systems:
 - ABS
 - EMS
 - HVAC
 - Instruments
 - Transmission
 - Steering / Suspension
- Supported functions:
 - Reads and deletes DTCs
 - Shows live data
- Models affected:

– B-Max	2012	– Kuga	2013
– C-Max	2015	– Kuga	2017
– Ecosport	2013	– Ranger	2015
– Edge	2016	– S-Max	2016
– Fiesta	2013	– Transit	2012
– Fiesta	2017	– Transit	2014
– Focus	2015	– Transit	2016

Service functions added:

- Supported functions:
 - Steering angle calibration, EPB service functions, TPMS sensor training mode, oil change and reset
 - DPF regeneration, high pressure injection pump replacement, SCR/Ad-Blue service functions
 - Vehicle speed limit configuration
- Models affected:

– C-Max	2011-...	– Kuga	2017-...
– C-Max	2015-...	– Mondeo	2007-...
– Ecosport	2013-...	– Mondeo	2014-...
– Edge	2016-...	– Ranger	2012-...
– Fiesta	2008-...	– Ranger	2015-...
– Fiesta	2013-...	– S-Max	2006-...
– Fiesta	2017-...	– S-Max	2016-...
– Focus	2011-...	– Transit	2002-...
– Focus	2015-...	– Transit	2006-...
– Galaxy	2006-...	– Transit	2012-...
– Ka	2016-...	– Transit	2014-...
– Kuga	2008-...	– Transit	2016-...
– Kuga	2013-...		

User interface improvements

- Automatic system detection improved

* This basic product information provides general information about products which may not (yet) be included in the product portfolio but are basically available. Versions and functionalities can deviate from this general information. All rights for the patent, utility model or design registration are reserved.

VDO



Service can be this easy

Renault

Extended EMS coverage:

- Supported functions:
 - Reads and deletes DTCs
 - Shows live data
 - Service functions (injector programming)
 - Configuration or resets of components:
 - Oil change interval
 - Particle filter adaptives
 - Throttle limits
 - Rail pressure sensor
 - Speed limiter (only commercial vehicles)
 - Stop and start function
- Models affected:
 - Twingo II 2007–2014
 - Duster 2010-...
 - Duster 2011-...
 - Duster Box 2011-...
 - Kadjar 2015-...
 - Captur 2013-...
 - Clio IV 2012-...
 - Clio IV Grandtour 2013-...
 - Dokker 2012-...
 - Dokker 2013-...
 - Dokker Express 2012-...
 - Logan II 2013-...
 - Logan II Estate 2013-...
 - Kangoo / Grand Kangoo 2008-...
 - Espace V 2015-...
 - Talisman 2013-...
 - Talisman Grantour 2016-...
 - Scenic IV 2016-...
 - Megane IV 2015-...
 - Megane IV Grandtour 2016-...
 - Traffic II Bus 2001-...
 - Traffic II platform/chassis 2001-...
 - Traffic II Van 2001-...
 - Modus / Grand Modus 2004-...

Extended ABS coverage:

- Supported functions:
 - Reads and deletes DTCs
 - Shows live data
 - Service functions (brake bleeding, steering angle sensor programming)
 - Configuration or resets of components
- Models affected:
 - Modus / Grand Modus 2004-...
 - Kangoo / Grand Kangoo 2008-...
 - Kangoo Express 2008-...
 - Traffic III Box/Bus/Van 2014-...
 - Duster 2010-...
 - Logan II 2013-...
 - Sandero/Stepway II 2013...

* This basic product information provides general information about products which may not (yet) be included in the product portfolio but are basically available. Versions and functionalities can deviate from this general information. All rights for the patent, utility model or design registration are reserved.

VDO



Service can be this easy

Opel

- Improved menu structure to simplify selection

Toyota

- Improved menu structure to simplify selection

BMW / MINI

- Model year update for CBS system (conditional based service)

New Vin Read Function

This function reads out the VIN from the vehicle. The Fastcheck functions from the menu that are not required for the detected vehicle will not be displayed. Also, the smarter menu now allows you to move between service functions without the need to select the same menu item.

Note:

- Not all vehicle supports this functions
- On some brands / models an ignition cycle is required to start communication to other ECUs after EOBD communication

* This basic product information provides general information about products which may not (yet) be included in the product portfolio but are basically available. Versions and functionalities can deviate from this general information. All rights for the patent, utility model or design registration are reserved.

VDO



Service can be this easy